

Consumable Electrode

SMAW – Shielded Metal Arc Welding

GMAW – Gas Metal Arc Welding


SAW – Submerged Arc Welding



Non-Consumable Electrode

GTAW – Gas Tungsten Arc Welding

PAW – Plasma Arc Welding



High Energy Beam

Electron Beam Welding

Laser Beam Welding



- Consumable electrode
- Flux coated rod
- Flux produces protective gas around weld pool
- Slag keeps oxygen off weld bead during cooling




Fig. 6


- General purpose welding—widely used
- Thicknesses 1/8" – 3/4"
- Portable

Power... Current I (50 - 300 amps)  
Voltage V (15 - 45 volts)

$$\text{Power} = VI \approx 10 \text{ kW}$$


SMAW - DC Polarity

Straight Polarity



Shallow penetration  
(thin metal)


Reverse Polarity



Deeper weld penetration


AC - Gives pulsing arc

- used for welding thick sections



- MIG - Metal Inert Gas
- Consumable wire electrode
- Shielding provided by gas
- Double productivity of SMAW
- Easily automated


- DC reverse polarity - hottest arc
- AC - unstable arc






- Consumable wire electrode
- Shielding provided by flux granules
- Low UV radiation & fumes
- Flux acts as thermal insulator
- Automated process (limited to flats)
- High speed & quality (4 – 10x SMAW)
- Suitable for thick plates

- 300 – 2000 amps (440 V)





- a.k.a. TIG - Tungsten Inert Gas
- Non-consumable electrode
- With or without filler metal
- Shield gas usually argon
- Used for thin sections of Al, Mg, Ti.
- Most expensive, highest quality

- Laser beam produced by a CO<sub>2</sub> or YAG Laser
- High penetration, high-speed process
- Concentrated heat = low distortion
- Laser can be shaped/focused & pulsed on/off
- Typically automated & high speed (up to 250 fpm)
- Workpieces up to 1" thick



Typical laser welding applications :

- Catheters & Other Medical Devices
- Small Parts and Components
- Fine Wires
- Jewelry
- Small Sensors
- Thin Sheet Materials Down To 0.001" Thick





Friction Welding

Diffusion Welding


Ultrasonic Welding

Resistance Welding





- One part rotated, one stationary
- Stationary part forced against rotating part
- Friction converts kinetic energy to thermal energy
- Metal at interface melts and is joined
- When sufficiently hot, rotation is stopped & axial force increased






## Resistance Welder Manufacturers' Association

*Joining Together to Promote Resistance Welding Excellence*

Resistance Welding is the coordinated application of electric current and mechanical pressure in the proper magnitudes and for a precise period of time to create a coalescent bond between two base metals.

- Heat provided by resistance to electrical current ( $Q=I^2Rt$ )
- Typical 0.5 – 10 V but up to 100,000 amps!
- Force applied by pneumatic cylinder
- Often fully or partially automated
  - Spot welding
  - Seam welding







## Resistance Welder Manufacturers' Association

*Joining Together to Promote Resistance Welding Excellence*


Resistance Welding is the coordinated application of electric current and mechanical pressure in the proper magnitudes and for a precise period of time to create a coalescent bond between two base metals.



- Heat provided by resistance to electrical current ( $Q=I^2Rt$ )
- Typical 0.5 – 10 V but up to 100,000 amps!
- Force applied by pneumatic cylinder
- Often fully or partially automated
  - Spot welding
  - Seam welding





- Parts forced together at high temperature ( $< 0.5T_m$  absolute) and pressure
- Heated in furnace or by resistance heating
- Atoms diffuse across interface
- After sufficient time the interface disappears
- Good for dissimilar metals
- Bond can be weakened by surface impurities



## Soldering & Brazing

- Only filler metal is melted, not base metal
- Lower temperatures than welding
- Filler metal distributed by capillary action
- Metallurgical bond formed between filler & base metals
- Strength of joint typically
  - stronger than filler metal itself
  - weaker than base metal
  - gap at joint important (0.001 – 0.010”)
- Pros & Cons
  - Can join dissimilar metals
  - Less heat - can join thinner sections (relative to welding)
  - Excessive heat during service can weaken joint





## Soldering

**Solder** = Filler metal

- Alloys of Tin (silver, bismuth, lead)
- Melt point typically below 840 F



**Flux** used to clean joint & prevent oxidation

- separate or in core of wire (rosin-core)

**Tinning** = pre-coating with thin layer of solder

Applications:

- Printed Circuit Board (PCB) manufacture
- Pipe joining (copper pipe)
- Jewelry manufacture
- Typically non-load bearing



Easy to solder: copper, silver, gold

Difficult to solder: aluminum, stainless steels

(can pre-plate difficult to solder metals to aid process)




## Manual PCB Soldering

PTH - Pin-Through-Hole connectors




- Soldering Iron & Solder Wire

- Heating lead & placing solder



- Heat for 2-3 sec. & place wire opposite iron




- Trim excess lead

## Automated Reflow Soldering

SMT = Surface Mount Technology

- Solder/Flux paste mixture applied to PCB using screen print or similar transfer method

- Solder Paste serves the following functions:
  - supply solder material to the soldering spot,
  - hold the components in place prior to soldering,
  - clean the solder lands and component leads
  - prevent further oxidation of the solder lands.



*Printed solder paste on a printed circuit board (PCB)*

- PCB assembly then heated in “Reflow” oven to melt solder and secure connection

## Brazing

Use of low melt point filler metal to fill thin gap between mating surfaces to be joined utilizing capillary action

- Filler metals include Al, Mg & Cu alloys (melt point typically above 840 F)
- Flux also used
- Types of brazing classified by heating method:
  - Torch, Furnace, Resistance

Applications:

- Automotive - joining tubes
- Pipe/Tubing joining (HVAC)
- Electrical equipment - joining wires
- Jewelry Making
- **Joint can possess significant strength**




Figure 7. Typical brazed pipe/tube applications. (Photo courtesy of Handy & Harman)



Figure 11. Typical brazing filler metal preforms. (Photo courtesy of Handy & Harman)

## Brazing

Use of low melt point filler metal to fill thin gap between mating surfaces to be joined utilizing capillary action

- Filler metals include Al, Mg & Cu alloys (melt point typically above 840 F)
- Flux also used
- Types of brazing classified by heating method:
  - Torch, Furnace, Resistance

Applications:

- Automotive - joining tubes
- Pipe/Tubing joining (HVAC)
- Electrical equipment - joining wires
- Jewelry Making
- **Joint can possess significant strength**




Figure 9. Typical carbide cutting tools brazed to metal in a brazing furnace. (Photo courtesy of Handy & Harman)

## Brazing

### Figuring length of lap for flat joints.


X = Length of lap

T = Tensile strength of weakest member

W = Thickness of weakest member

C = Joint integrity factor of .8

L = Shear strength of brazed filler metal



Problem: What length of lap do you need to join .050" annealed Monel sheet to a metal of equal or greater strength?  
 Let's see how this formula works, using an example.

Solution:

C = .8 T = 70,000 psi (annealed Monel sheet)

W = .050"

L = 25,000 psi (Typical shear strength for silver brazing filler metals)

X = (70,000 x .050) / (.8 x 25,000) = .18" lap length

## Brazing

### Figuring length of lap for tubular joints.


X = Length of lap area

W = Wall thickness of weakest member

D = Diameter of lap area

T = Tensile strength of weakest member

C = Joint integrity factor of .8



Again, an example will serve to illustrate the use of this formula. Problem: *What length of lap do you need to join 3/4" O.D. copper tubing (wall thickness .064") to 3/4" I.D. steel tubing?*

Solution: L = Shear strength of brazed filler metal

W = .064"

D = .750"

C = .8

T = 33,000 psi (annealed copper)

L = 25,000 psi (a typical value)

$X = (.064 \times (.75 - .064) \times 33,000) / (.8 \times .75 \times 25,000)$

X = .097" (length of lap)